

Analysis of Lightning-Caused Distribution Transformer Failures

**T. O. de Carvalho, A.
Piantini, P. F. Obase**

Institute of Electrotechnics and
Energy / University of São
Paulo - São Paulo, Brazil
thais@iee.usp.br,
piantini@iee.usp.br,
pfobase@iee.usp.br

J. M. Janiszewski

Polytechnic School / University
of São Paulo
São Paulo, Brazil
jorge@lcs.poli.usp.br

E. L. Batista

AES SUL
São Leopoldo, Brazil
edson.batista@aes.com

This paper investigates the effects of direct strokes to medium-voltage (MV) lines by analyzing the surges at the primary and secondary sides of a single-phase distribution transformer installed in a typical rural network of the state of Rio Grande do Sul, located in the South of Brazil. The distribution transformers of AES Sul, the electric utility, present a high failure rate and a significant number of the failures are attributed to lightning. The transformers are in general protected by surge arresters at the MV terminals and in a few cases also at the low-voltage (LV) side. Different distances between the MV arrester and the transformer as well as various values of ground resistance are considered in the analysis.